

Johns Creek Jetty Condition 12/2/2019

Internal frame on headstock



Main Frame / headstock fastenings



Fender Brackets



Main Frame Jetty foundation attachment



Fibreglass Matting to Frame support.



Steel fragments



Ramp condition May 2010

